


① BOX UNFOLDED, PAPER THINE IN PLACE. BAG FLAPS TO BE FRESH SIDE DOWN WITH CLEAN TAGS & LOOSE ENDS IN THE CENTER.



② RAISE & HOLD SIDES




③ RAISE ENDS, CLOSING AND LOCKING THE BOX. TIE FLEECES.




④ RELEASE ENDS, UNFOLDING BOX, WEIGH, TAG, AND PACK FLEECE IN WOOL BAG.

OPERATION OF THE WOOL BOX



CUTTING & ASSEMBLY DIAGRAM



PLAN EX. 5806 SHOWS DETAILS OF A WOOL PACKING BAG WHICH HOLDS THE WOOL BAG IN A CONVENIENT POSITION.

NOTES:  
1. DIMENSIONS SHOWN ARE BASED ON USE OF STANDARD 1 1/2" LUMBER DRESSED. THIS IS ADEQUATE FOR FLEECES OF 8 TO 10 POUNDS.  
2. THE PLAN MAY BE MODIFIED AS DESIRED TO SUIT INDIVIDUAL PREFERENCES.  
3. ALL WOOD PARTS SHOULD BE Sanded & CORNERS SMOOTHLY ROUNDED. REMOVE CORNERS & BURRS FROM METAL PARTS TO AVOID SAGGING WOOL.